SAFETY OBSERVATION REPORT

Observers: P. Pile, S. LaMontagne, E. Lessard			Date: 6/28/07	Duration: 1.5 Hr.	RHIC Ring	9		
Observation Categories	Observation	Ouestions:		•				
POS	In risky position relative to task? Exposed to risks of temperature/electricity/gas/chemicals/radiation? Protection OK?							
ERG	Risks from: posture, repetitive motion, load, vibration, temperature, lighting, noise, work flow?							
PPE	Correct PPE? In safe condition? All parts of the body properly protected?							
T&E	Is tool, equipment or facility right for the job? In safe condition? Used correctly?							
PRO	Is there a standard procedure? Is p Followed?				ocedure adequate	? Up to date?	Un	derstood?
ORD	Is workplace orderly? Adequate space? All in its place?							
ASF	No unsafe acts of							
Work Area or Location	Number of Contacts	Description	n of unsa		Observation Category	Follow-up Action	Person Responsible	By Date
PHENIX work area	4	Positive: Stude building scine were clearly and PPE requestrated that area were assures were for visiting them. Although it will due to delays room in B912 and hazards were students.	dents/collab tillation dete familiar with irements. T t C-AD tech isting in ens llowed, and on a regular was an ad ho in setting up 2, the work w	orators were extors and in hazards They inicians in suring BNL were in basis. It work area in a clean was planned	ASF			
Unsafe conditions	0	Lights at the 7GE1 gate and stairway were completely out.			ASF	Temporary lighting should be made readily available until overhead lighting is fixed.	R. Zaharatos	ASAP

COMMENT: The management team noted portions of the tunnel were poorly air conditioned. About 20 to 30% of RHIC magnets, electronics and power distribution devices are soaking wet due to the humidity.